

Before performing any service always follow applicable safety precautions.

Dual Damper Smoke Extractor (#593001)

Affected Products: Gas smoker models; BBR series - 79 & 700
SPK series - 280,500*,700,1400**
XLR series - 350,600,1000,1400,1600 & 1600-4
UXR series - 100
* 500 smokers without "K" in the serial number
** 1400 smokers built prior to 2016.

Affected Serial Range: N/A


Related Issue #: N/A

Issue Description:

The dual damper smoke extractor (#593001) is now obsolete.

Actions Required:

The single removable damper smoke extractor (#593004) can be installed on units that were equipped with the dual damper smoke extractor (#593001) with the use of adaptor (#593014) . This is pictured below:



Actions Required (continued): The single damper smoke extractor is 2 1/4" (57mm) taller than the dual damper smoke extractor and the adapter is 4" (102mm) tall, this will require some adjustment to the length of the exhaust duct. The actuator motor of the single damper smoke extractor does not have a port for the conduit connection for the smoke extractor exhaust fan; some modification will be required.

Additional Comments:

Secondary Distribution:

Service technicians within the Distributor's organization.

Service companies.

For Additional Information:

Southern Pride Technical Service: (800) 437-2679