



SERVICE BULLETIN

SP2016-001

Revision 1

July 1, 2019

Before performing any service always follow applicable safety precautions.

Product Door Gasket Lengths

Affected Products: Current models (as of July 2019)
Affected Serial Range: N/A
Related Issue #: N/A
Revision 1: Removed SC-200, DH-65 and SPK-1000
 Added SC-300
 Changed SP-700 length

Issue Description:

The appropriate product door gasket lengths for cutting bulk gasket (part number 070002) to size.

Actions Required:

Part Number	Model	Product Door Opening Length	Z bracket (on door) length
070102	SC-300	120" 3048mm	N/A
070092	SRG-400	138" 3505mm	N/A
070088	MLR-150	81 1/2" 2070mm	N/A
070080	SPX-300	107"	21"
070081	SPK-500 "K" in s/n	134 1/2" 3416mm	21" 533mm
070089	SP-700	152" 3861mm	27" 686mm
070090	MLR-850	100" 2540mm	N/A
070101	SPK-1400	139 1/2" 3543mm	27" 686mm

Additional Comments:

The customer may need to trim the gasket to achieve their desired fit.

Secondary Distribution:

Service technicians within the Distributor's organization.

Service companies.

For Additional Information:

Southern Pride Technical Service: (800) 437-2679