



# SERVICE BULLETIN

SP2016-001  
 Revision 0  
 February 19, 2016

Before performing any service always follow applicable safety precautions.

## Product Door Gasket Lengths

**Affected Products:** Current models (as of February 2016)  
**Affected Serial Range:** N/A  
**Related Issue #:** N/A

### Issue Description:

The appropriate product door gasket lengths for cutting bulk gasket (part number 070002) to size.

### Actions Required:

Part Number	Model	Product Door Opening Length	Z bracket (on door) length
070024	SC-200	113" 2870mm	N/A
070024	DH-65	113" 2870mm	N/A
070092	SRG-400	138" 3505mm	N/A
070088	MLR-150	81 1/2" 2070mm	N/A
070080	SPX-300	107"	21"
070081	SPK-500	134 1/2" 3416mm	21" 533mm
070089	SP-700	151" 3835mm	27" 686mm
070090	MLR-850	100" 2540mm	N/A
070076	SPK-1000	131" 3327mm	21 1/2" 546mm
070101	SPK-1400	139 1/2" 3543mm	27" 686mm

**Additional Comments:**

The customer may need to trim the gasket to achieve their desired fit.

**Secondary Distribution:**

Service technicians within the Distributor's organization.

Service companies.

**For Additional Information:**

Southern Pride Technical Service: (800) 437-2679